ENVIRONMENTAL COMPLAINTS & LOCAL SERVICES TOTAL RETENTION FACILITIES

TOTAL RETENTION FACILITIES with LAND APPLICATION WASTEWATER BYPASS FORM

deur littrative prosperous Okiahoria	2 70 40
NEO E III ID	2000

Facility Name:

KURU WOHLT & Sewer County:

Pittsburg 20

Report all Total Retention Facility and
Total Retention Facilities with Land Application
wastewater bypasses to
EQ/Environmental Complaints and Local Service

DEQ/ Environmental Complaints and Local Services within **24 hours** at:

1-800-522-0206

Mail or Fax written report including copies of ANY test results.

within 5 days to:

Department of Environmental Quality

Department of Environmental Quality Environmental Complaints and Local Services P.O. Box 1677

Oklahoma City, OK 73101-1677 Fax No. (405) 702-6226

DEQ notified:	3 7	2018		<u> </u>	М 🗌 РМ		
Period of bypass:	From ϕ_{Month}^{3}	₫7	2018	11: ØØ	_ 🔀 AM	☐ PM	
						□РМ	
Type of Bypass:	☐ Pipe 🔀 La				Head Works	; <u> </u>	Lift Station
Strength of Bypass	Raw] Partially Trea	ated A	mount of F	Bypass: 3	000 00	DO GALLOWS
	aken: BOD T				(X) Othe	r: TUTHL G	JUNEAY SINUTION
Geographical loca	tion of bypass and re	eceiving stream	m if appropria	ite:		τ, ωι	.) >
	33.46"/wo						
Reason for bypass	CONTROLLED BY	DASS TO REA	nory RAINV	ATON I	AND AND	10 FURN	LY UNCONTROLLAD,
	vent recurrence: TES						
Were fish or other	wildlife affected as	a result of the	bypass?	Yes 🔀	lo How?_		
Impact to receivin	g stream and /or sur	ounding areas	s: NONE				gaing gaile the second
Steps taken to clea	an up or treat bypass:	LIMB	DATE:				
Reported by:	aci aven		Title: _	adn	$\sim \sim$	Mager	
Signature:	a allen					7	
DEQ EPS USE ONLY:	Facility Representative	# ·					
-						🗀 ৯	
							ate:
	: <u> </u>						
	vent recurrence:						
•	g stream and/or surro	_					
	an up or treat bypass:						
	needed:						
Reported informat	tion confirmed: Y	'es ∐ No If n	o, explain:				
Comments:							
							